



Release Notes for Drivers Pack 3.2.7

Drivers Pack 3.2.7 is recommended to use with the base products Axxon Intellect Enterprise v.4.8.2 or Axxon Smart PRO v.2.1

New integrations of IP-devices

- Arecont Vision AV1115/-DN/-AI
- Arlotto AR1500/-H/-T
- Arlotto AR2200/-H/-T
- Arlotto AR2500/-H/-T
- Arlotto AR2510
- Arlotto AR2520
- Arlotto AR3210
- Arlotto AR3510
- Arlotto AR4200/-H/-T
- Arlotto AR4500/-H/-T
- Brickcom GOB-130Np
- Brickcom OB-130Np
- Brickcom WOB-130Np
- Hikvision DS-2CD754F-E
- Hikvision DS-2CD783F-E
- Hikvision DS-2CD8133F-E
- Hikvision DS-2CD8153F-E
- Hikvision DS-2CD854F-E
- Hikvision DS-2CD864FWD-E
- Hikvision DS-2DF1-401H
- Hikvision DS-2DF1-516
- Hikvision DS-2DF1-514
- Hikvision DS-2DF1-572
- Hikvision DS-2DF1-714
- Hikvision DS-2DF1-716
- Hikvision DS-2DF1-718
- Hikvision DS-2DZ216
- ITV WS-216
- Messo NCB855pro
- Messo NCR875pro
- Messo NDF820
- Messo NCR870/-H
- Messo NDF831/-H
- Messo NDR891/-H
- MOXA Vport 461
- Sentry360 FS-IP5000

Installation

For updating installation start file **IPDriverPack.msi**.

Installation of updating requires to restart base software and remove previous version of Drivers Pack. Version of Drivers Pack before 3.2.1 requires to remove by «Add/Remove Programs».

More details about supported functions and supported firmware for each IP-device look on a site of the manufacturer at the list of supported IP devices for version of the base product.

www.itv.ru

www.axxonsoft.com